

Comparison of Chip numbers on two different sets of Epson Carts Pro 3880

	5808 MK	5801 PK	5807 LK	5809 LLK	5802 C	580A M	5805 LC	580B LM	5804 Y
Present Set									
Chip numbers	F2106	F22884	F2183	F22817	F2163	F2173	F2160	F2165	F2130
functioning	ok	ok	ok	ok	ok	ok	ok	ok	ok
New Set									
Chip numbers	F2147	F2108	F2141	F2140	F2163	F2103	F2127	no chip	F2123
	ok	ok	not	not	ok	not	not		not

Conclusion

All are different except those on the two 5802 carts

Of the 8 carts 2 did function correctly with different chip numbers